

Attachment C - Staff Report SRPBS.25.002



Figure 1 May 2024 photograph of 159 Mill Street showing the historical (south) portion of the building, with a later rear addition visible on the right. All identified heritage attributes are limited to the historical portion of the building, including the house's one-storey massing, hipped roof with wide eaves, symmetrical three bay front façade with a centered doorway, and the appearance of clapboard siding and 12-over-12 windows (Source: HUD 2024).



Figure 2 1978 archival photograph of 159 Mill Street showing the historical (south) portion of the building (Source: Richmond Hill LACAC).