'Appendix A' to Staff Report SRPI.23.036

Last Updated: January 1, 2022



Heritage Permit Application

Property Information

This permit form is for applicants proposing alternations to individually designated properties, cultural heritage landscapes and properties located within a heritage conservation district. Applicants are strongly advised to consult with the Heritage Planner to confirm if the work to be undertaken requires a Heritage Permit.

Attachments to this application should include all the supporting documents that will provide the necessary visual or technical information by which the project can be properly evaluated. Applicants are strongly advised to consult with the Heritage Planner prior to formally submitting their application to confirm whether additional reports or studies are required. The City only accepts applications that are complete as confirmed by the Heritage Planner.

Although it is not required to obtain professional assistance in the preparation of this application, applicants are **strongly advised** to seek such assistance from an architect, architectural technologist, preservation specialist, or others familiar with the unique requirements of designated heritage properties.

Municipal Address:___1300 Elgin Mills Road East, Richmond Hill, ON L4S 1M5 Legal Description: Existing Use: Residential Commercial Institutional Other Owner & Agent Information **Property Owner** City of Richmond Hill (Project Manager: Andrew Beshay) Name of Owner: Email: andrew.beshay@richmondhill.ca 905-771-5502 Phone Number: Address: Agent (if applicable) Name of Agent: Ryan Lee Business Phone: 647-454-0084 Fax: N/A Email Address: ryan@ataarchitectsinc.com Address and/or location of designated property if different from the address above: Individual Designation By-Law Number (Part IV) - By-Law Number: 17-93 Located within the Gormley Heritage Conservation District (Part V): Yes No

Required Supporting Documents

Built Heritage Projects

1. Written Description

Describe the work to be undertaken. This must include a description of the property and its location, the work to be undertaken, construction methods and means of attachment, materials and colour to be used, potential impacts to the property's heritage attributes, and reasons why the City should approved this application.

2. Scaled Drawings

Submit scaled drawing(s) in 11"x17" or 8"x11" size illustrating the existing condition and the proposed alteration. The scaled drawing(s) for built heritage projects must include:

- Overall dimensions:
- Labelling of building elements (signs, windows, awnings, etc.) and their dimensions;
- Detailed architectural information (trim, siding, etc.) with dimensions and profiles;
- Types of material and colour to be used (MUST be noted on drawing to indicate their location); and
- Construction methods and means of attachment.

3. Photographs

Photographs of the buildings including general photos of the following:

- Heritage features and any areas that are affected by the proposed alteration or change;
- All elevations of the building;
- Streetscape in which the building is facing;
- Streetscape in which the building is located; and
- If a property is located at an intersection, all four corners of the intersection.

4. Site Plan & Construction Plans

Submit site plan identifying the property boundaries and footprints of existing and proposed (if applicable) buildings with distances from adjacent properties and location of proposed work. Include construction plans illustrating the proposed work.

5. Historical Documentation

Submit any historical documents (i.e. photographs, articles) on the subject property that will assist the City to understand the application.

6. Additional Studies

Submit any additional technical cultural heritage studies that are relevant to the proposed alteration, if required.

Cultural Heritage Landscapes

For proposed alterations to designated cultural heritage landscapes, please contact the Heritage Planner for the required supporting documentation.

Fees

Minor Work: \$406

Definition: Minor alterations are defined as small additions, repairs or similar changes. Generally, they do not impact the identified heritage attributes of a property.

Major Work: \$3,480

Definition: Major applications alter or remove identified heritage attributes of a property. This includes the relocation of a structure to a different part of the property, the dismantling of a structure to be incorporated within a new structure, an addition to an existing heritage structure, and any changes affecting the legal description of the property as contained in the designation by-law.

Payments can be made via a cheque made out to the City of Richmond Hill Planning and Infrastructure.

Declaration

Declaration: I	Ryan Lee	of the City/Town of_	Burlington	solemnly
declare that I a	am the Owner [] or the Authorized age			property and that all
the information	n and statements provided in this app	lication form and on the	attached drawings a	nd specifications are
to the best of r	my knowledge and belief true and I ma	ake this Solemn Declarat	ion conscientiously b	pelieving it to be true,
and knowing it	is of the same force and effect as if r	nade under oath, and by	virtue of the Canadi	an Evidence Act.
Signature of a	oplicant:		Date: 20)23 02 28

The personal information of this form is collected under the legal authority of Section 33(2) and Section 42(2) of the *Ontario Heritage Act*. The information will be used for the purposes of administering the heritage permit application and ensuring appropriate service of notice of receipt under Section 33(3) and Section 42(3) of the *Ontario Heritage Act*. If you have any questions about this collection of personal information, please contact the Heritage and Urban Design Planner, Pamela Vega, at 905-771-5529.

Heritage Permit Application – Required Supporting Documents

1. Written Description

Overview

The proposed work to be undertaken is the exterior restoration of the building facade of the Boynton House as part of the City of Richmond Hill's ongoing maintenance repairs to City-owned heritage buildings.

The following interventions are proposed for the building's exterior facade:

- Repair door sills
- Repair wood trim
- Repair window frame
- Regrade around basement window

Restoration of Wood Windows and Doors

The window restoration is for four basement windows on the East and west sides. The area around the basement window is to be regraded so that the grade is 4" below the sill and also slope the grade away from the building.

The basement windows also have areas wood deterioration and damage due to cracks or hardware holes, re-seal the joints between the upper and side window and frame where they are pulling apart, and fix areas of failing window glaze putty. Areas of wood deterioration and rot will be repaired using epoxy or the Dutchman's patch method. Holes in the window frame and sills will similarly be filled in with an epoxy repair system. All wood windows frames are to be repainted with selected shades to match existing colour.

In addition to the repairs to their window frames, the basement windows will also require the replacement of their concrete window sills which have become significantly deteriorated. They will be replaced with a concrete sill that will match the concrete sill beneath the basement window at the far south of the west elevation.

For the Door restoration, The Front and secondary entrances are to have the wood sills below removed and replaced to match existing. The sills, doors and frames are to be repainted with selected shades to match existing colour.

Repairs to Wood Trims

The proposed repairs to the heritage wood elements include areas of damage to the wood trim at the base of the front porch columns as noted on the architectural drawings. The damaged base trims are to be removed and replace with new to match existing. Column base and trims are to be repainted with selected shades to match existing.





DRAWING LIST				
	SHEET NAME	ISSUED FOR HERITAGE PERMIT	ISSUED FOR TENDER	
#	SHEET NAME	HERITAGE PERMIT	IENDER	
A-8H0.1	COVERSHEET & DRAWING LIST	X	Х	
A-BH2.1	BUILDING PLANS	X	X	
A-BH3.1	NORTH & SOUTH ELEVATIONS	X	X	
A-BH3.2	EAST ELEVATION	X	X	
A-BH3.3	WEST ELEVATION	Y	Y	




MATERIAL SCHEDULE PTO1 - PAINT TYPE 1 - NEW PAINT - DOOR MANUFACTURE: ALBACK LINSEED OIL PAINT OR APPROVED EQUAL

ALLBACK LINSELU OIL PRINT OF THE THREE TO BEET TO SPECIAL TO CONFIRM, TO BE SELECTED FROM MANUFACTURERS RULL RANGE (ALLOW FOR UP TO S COLOURS WITHIN THESE SPACES, 5 SAMPLES OF EACH) REFER TO DRAWINGS

PDA - PANITYPE 4 - NEW PANIT-TRIM PANIT
MANUFACTURE: ALBACK URBERT OIL PINNT OR APPROVED EQUAL
COLOUR: ARCHITECTURE OF THE OFFICE OF SECRET BROWN MANUFACTURERS RALL BANGE
ALLOW FOR UP TO S COLCURS WITHIN THESE SPACES, S SAMPLES OF EACH
COCATION: SEETE TO DIOANNICS.

CS01 - PRECAST CONCRETE SILL SUPPLIER: -




BOYNTON HOUSE RESTORATION ISSUE FOR TENDER

1300 ELGIN MILLS ROAD, RICHMOND HILL, ON

PROJECT NO. 22-1514B

ARCHITECTURAL

ATA ARCHITECTS INC.
3221 NORTH SERVICE ROAD. SUITE 101
BURLINGTON ONTARIO L7N 3G2
T 905-849-6986





BOYNTON HOUSE RESTORATION

1300 ELGIN MILLS ROAD, RICHMOND HILL, ON

COVERSHEET & DRAWING LIST

RL, KS


As indicated

2023 02 28

22-1514B

A-BH0.1

KEY PLAN - SITE PLAN




122. 1514 - Richmand HI - Mill Hause, Boyman Hause, Shaw Hause 102-Construction Documents 101-Architec











FACADE RESTORATION LEGEND:

STRIP PAINT TO ASSESS PULL EXTENT OF DAMAGE TO WOOD FRAME. IF DAMAGE IS SHALLOW, FILL IN CRACKS OR HOLES WITH SEA ALM IF DAMAGES BEFORE DEFORE DEFORMER, BEFLACE DAMAGED SECTION OF WOOD OLD OUT OF DAMAGED SECTION OF WOOD DOWN DOWN SOURCE OF FARE OUT NEW WOOD BOARDS TO MATCH PROFILE OF EXISTING SIDING AND SIZE OF AREA TO BE REPLACED, AND SECURE IN PLACE.

REGRADING AROUND BASEMENT WINDOW

REMOVE GRADE AROUND BASEMENT WINDOW TO 4" BELOW SILL. REGRADE AREA TO SLOPE AWAY FROM BUILDING.

A3 NEW PRECAST WINDOW SILL
REPLACE CONCRETE SILL WITH NEW R

DOOR SILL REPLACEMENT

EXISTING DOOR SILL TO DOCT EXISTING DOOR SILL TO BE REMOVED AND REPLACED WITH NEW DOOR SILL REPAINT TO MATCH EXISTING

REMOVE LOOSE AND/OR DAMAGED WOOD TRIM BOARD AND REPLACE WITH NEW WOOD TRIM. CUT OUT DAMAGED SECTION AND REPLACE. ENSURE NEW SECTION IS LEVEL, MATCH EXISTING PROPRIE

PAINTING LEGEND:

WOOD DOOR/DOOR FRAME/ WINDOW FRAME/ SILLS/ TRIMS (ETC.) REPAINTING
STIP PART TO THE RESE WOOD AND PAICH AND DEPAR ANY CRACKS. HADDWARE HOLES DO
DAMAGE PARKES AN ROSESWY FRAME WOOD SHEEKE ARP AY RESENTATION TO WOOD AND
REPART IN THER DIRIESTY OF THE EVEROR AND INTEROR OF THE DOORS, FRAMES AND WINDOW TO
MACH THE SISTIMN COLOUR.





BOYNTON HOUSE RESTORATION

1300 ELGIN MILLS ROAD, RICHMOND HILL, ON

NORTH & SOUTH ELEVATIONS


As indicated


RL, KS

2023 02 28

22-1514B

A-BH3.1









2023 02 28 ISSUE FOR HERITAGE PERMIT/TENDER 2023 02 21 ISSUE FOR REVIEW **BOYNTON HOUSE** RESTORATION 1300 ELGIN MILLS ROAD, RICHMOND HILL, ON EAST ELEVATION RL, KS As indicated 2023 02 28 22-1514B

A-BH3.2

P.122-1514 - Retmond HI - MII House, Boymon House, Shaw House 102-Construction Documents (01-Architectural

M202000-01 320-00 PM





2023 02 28 ISSUE FOR HERITAGE PERMIT/TENDER 2023 02 21 ISSUE FOR REVIEW NUMBER DATE REMARK CONTRACTOR IS TO CHECK AND VERIFY ALL DIMENSIONS AND CONDITIONS ON THE PROJECT AND REPORT ANY DISCREPANCIES TO THE ARCHITECT EFFORE PROCEEDING WITH THE WORK, DRAWINGS ARE NOT TO BE SCALED. **BOYNTON HOUSE** RESTORATION 1300 ELGIN MILLS ROAD, RICHMOND HILL, ON WEST ELEVATION RL, KS As indicated 2023 02 28 22-1514B

A-BH3.3

P.122 1514 - Retmand HL - Mil House, Boymon House, Show House 102 Construction Documents 101-Ar

2 A.BH3.3 1 : 25

APPROXIMATE AMOUNT OF PAINT STRIPPING - FRAME 70% - WINDOW 70% - WINDOW 70% - APPROXIMATE AMOUNT OF REPUTTYING: - WINDOWS 25%



South/ Front Elevation



East Elevation at South



East Elevation at North




North/ Rear Elevation



West Elevation at North



West Elevation at South



View of Main Enterance



View of Second Enterance



View of Base of West Porch Column



View of Base of East Porch Column



View of Basement Window East Elevation



View of Basement Window West Elevation


Heritage Permit Application - Site Photographs 1300 Elgin Mills Road East, Richmond Hill, ON



Streetscape North of Elgin Mills Road East - Subject Property at 1370 Elgin Mills Rd E



Streetscape North of Elgin Mills Road East - Neighbouring Landscape



Streetscape North of Elgin Mills Road East - Neighbouring Landscape and Parking

Heritage Permit Application - Site Photographs 1300 Elgin Mills Road East, Richmond Hill, ON



Streetscape South of Elgin Mills Road East - Building Across the Street at 8 Danpatrick Dr.



Streetscape South of Elgin Mills Road East - Building at 21 Matteo David Dr



Streetscape South of Elgin Mills Road East - Building at 1365 Elgin Mills Rd E