

## Extract from Heritage Richmond Hill Meeting HRH#04-24 held April 4, 2024

## 6. Scheduled Business

## 6.7 SRPBS.24.040 - 2024 Heritage Grant Applications - 7 Properties

Moved by: A. Parr

That Heritage Richmond Hill recommends to Council:

- a) That a Heritage Grant in the amount of \$5,000 be approved towards the cost of reconstructing the west verandah of the property located at 16 Bawden Drive (designated under Part IV of the *Ontario Heritage Act*), as outlined in staff report SRPBS.24.040;
- b) That a Heritage Grant in the amount of \$5,000 be approved towards the cost of repairing the cupola of the property located at 38 Bedford Park Avenue (designated under Part IV of the *Ontario Heritage Act*), as outlined in staff report SRPBS.24.040;
- c) That a Heritage Grant in the amount of \$3,800 be approved towards the cost of replacing seven windows of the property located at 146 Gormley Road West (designated under Part V of the *Ontario Heritage Act*), as outlined in staff report SRPBS.24.040;
- d) That a Heritage Grant in the amount of \$5,000 be approved towards the cost of emergency structural repairs to the west foundation wall of the property located at 151 Gormley Road West (designated under Part V of the *Ontario Heritage Act*), as outlined in staff report SRPBS.24.040;
- e) That a Heritage Grant in the amount of \$3,500 be approved towards the cost of replacing six windows of the property located at 188 Gormley Road West (designated under Part V of the *Ontario Heritage Act*), as outlined in staff report SRPBS.24.040;
- f) That a Heritage Grant in the amount of \$1,600 be approved towards the cost of emergency roof repairs to the garage of the property located at 217 Gormley Road West (designated under Part V of the *Ontario Heritage Act*), as outlined in staff report SRPBS.24.040;
- g) That a Heritage Grant in the amount of \$5,000 be approved towards the cost of repairing the Octagonal Vault of the property located at 10066 Yonge Street (designated under Part IV of the *Ontario Heritage Act*), as outlined in staff report SRPBS.24.040.

Carried Unanimously